Battery Compartment Security Cover Installation Instructions

Battery Compartment Security Cover – Materials List			
Alpha P/N	Description	Qty	
607-732-V1-001	Door, lift off, battery compartment	1	
607-733-V1-001	Bracket, shelf support, lift off door, battery compartment	1	
630-062-12	Scrw, mach (flathead), #10-32x1/2"	2	
651-001-19	Tie, cbl, 3-1/2" L	1	
746-865-C0-001	Instl instr, Ift off dr, w/ wld plt	1	

Weld Plate Kit – Materials List		
Alpha P/N	Description	Qty
607-734-V1-001	Plate, weld, lift off battery door	1
636-105-12	Rivet, POP, 0.125"DIA, 0.126" - 0.250"GRP, SST/SST	2

TOOLS REQUIRED:

#2 Phillips screwdriver

Personal Protective Equipment

5/16" Torque Wrench and Security Screw Key (only used for install method 1)

Welding equipment suitable for AISI 1018 CRS (only used for install method 2)

Rivet Tool (only used with weld plate kit and install method 2)






WARNING! GENERAL AND ELECTRICAL HAZARD


- Exercise EXTREME CAUTION when using tools on the enclosure and working around batteries.
- · Lead-acid batteries contain dangerous voltages, currents and corrosive material.
- Only authorized personnel are to perform installation, maintenance, service or replacement of the enclosure, power supply or batteries.

INSTALLATION PROCEDURE:

- 1. Remove the Tamper Switch Magnet.
- 2. Attach the optional weld plate to bottom of cabinet with supplied rivets.



Hardware Stackup Close Up



Overall View




Fig. 1, View from beneath, PWE Enclosure and Weld Plate







WARNING! ELECTRICAL HAZARD

If the security cover is being installed in an existing system, remove the batteries (with batteries disconnected, inverter functionality is not available) before installing the shelf support bracket to reduce the chance of the bracket causing a short circuit by coming into contact with the battery terminals.

Replace the batteries only after the bracket is securely attached to the shelf.

If the security cover is being installed in a new system, install the bracket before loading the batteries into the enclosure.

Fig. 2, Bracket Installation Detail

INSTALLATION PROCEDURE, continued:

- 3. Attach the shelf support bracket under the front edge of the upper shelf with the two 10-32 x 1/2" screws. Verify the notches on the bracket align with the existing notches of the shelf.
- 4. After attaching the support bracket, loading the batteries and connecting the battery cables, install the battery door by inserting the tabs of the battery door through the slots in the weld plate. Replace the Tamper Switch Magnet [1].
- 5. At this time, the installer may use one or both of the optional methods of securing the battery door to the enclosure.

Method 1:

Secure the battery door to the upper tray (4 places) by means of an Alpha Security Screw (p/n 647-189-11) or 5/16" - 18 x .75 (or equivalent) security screw. For optimal security torque the bolts to 17.63 Nm (13 ft/lbs).




Fig. 3, Fastening the Battery Door

Method 2:

Weld a continuous bead along either side of the tabs at the bottom of the enclosure to join the tabs to the weld plate (Fig. 4). After completing the welding procedure, protect the unpainted area by applying a corrosioninhibiting coating.

> Weld the tabs and plate together.




Fig. 4, Weld Seam Location

Worldwide Corporate Offices

North America Tel: +1 360 647 2360 Fax: +1 360 671 4936

Tel: +49 9122 79889 0 Fax: +49 9122 79889 21 **Latin America** Tel: +561 792.9651 Fax: +561 792.7157 **Asia Pacific** Tel: +852 2736.8663 Fax: +852 2199.7988